

Slumping Basics

PRODUCTS USED

- Uvex Safety Glasses ([008864](#))
- ACE Oversize Safety Glasses
- ACE Safety Glasses
- ACE Uptown Tortoise Safety Glasses
- Disposable Particulate Respirator N95, 20 pack ([008262](#))
- Disposable Particulate Respirator N100 ([008261](#))
- Hake Brush ([007014](#))
- Bullseye Shelf Primer ([008220](#))
- Ball Surface Mold ([008734](#))
- Lamp Bender Mold ([008725](#))
- Square Slumper A Molds ([008634](#)) ([008635](#))
- Seder Plate Mold ([008959](#))
- Drop Out Ring Molds ([008633](#)) ([008632](#)) ([008631](#))
- Slumping Molds ([008925](#)) ([008629](#)) ([008995](#)) ([008997](#)) ([008736](#)) ([008638](#)) ([008723](#)) ([008665](#)) ([008963](#))
- Fiber Paper ([007037](#)) ([007036](#))
- Triangular Kiln Posts (008888) ([008889](#))
- Kiln Dams & Bricks ([008882](#)) ([008893](#)) ([008896](#)) ([008897](#)) ([008898](#))

FIRING SCHEDULE

Slump Firing

	RATE	TEMPERATURE	HOLD
1	300° F (167° C)	1180° F (638° C)	0:05
2	AFAP*	900° F (482° C)	1:00
3	100° F (56° C)	700° F (371° C)	0:01
4	AFAP*	70° F (21° C)	0:00

*AS FAST AS POSSIBLE